

Trouble shooting black AA sensors

voltages for AutoAnchor 500C, AA560, AA150

- # Sensor wire must be screened
- # Joints must be soldered and sealed to prevent signal noise and water ingress
- # The use of crimp splices and spade connectors for sensor connection is not acceptable

