

Trouble shooting black AA sensors

voltages for AutoAnchor 500C, AA560, AA150

Sensor wire must be screened

Joints must be soldered and sealed to prevent signal noise and water ingress

The use of crimp splices and spade connectors for sensor connection is not acceptable

